# Strongcoat Topping Plus

Heavy duty epoxy topping for floor surfaces applied at 5 - 15 mm



# Description

Strongcoat Topping Plus is a three-pack solvent free, epoxy-based topping that provides floor surfaces with a seamless, hygienic and cosmetically attractive finish. Strongcoat Topping Plus is applied by trowel and can be coved and laid to falls and has a very good durability towards pedestrian and vehicular traffic.

It also has very good resistance towards many of the chemicals commonly found in an industrial environment (consult our Technical department for further details).

Strongcoat Topping Plus has a finish that provides very good slip resistance and can be supplied in a natural colour and variety of colours (consult our Sales Department for details).

# **Applications**

Strongcoat Topping Plus is used to provide a hygienic, dense and extremely hard wearing surface for concrete floors for a wide range of applications such as:

- ▲ Heavy industry factories.
- ▲ Paint workshops.
- ▲ Steel works.
- ▲ Dairies.
- ▲ Chemical factories.
- ▲ Oil refineries.
- ★ Freezers and refrigerated storage.

# **Advantages**

- ▲ Extremely hard wearing system.
- ▲ Solvent free.
- ▲ Non-slip.
- ▲ Available in a wide range of attractive colours.
- A Resist a wide range of chemicals, consult DCP technical department for more details.

#### **Standards**

Strongcoat Topping Plus complies with EN 13813, SR-B2.0-AR0.5-IR10.

Technica	l Properties	<b>@ 2</b>	5°C:
----------	--------------	------------	------

Specific gravity:  $2.1 \pm 0.1$ 

Pot life: 1 hr

Compressive strength: > 75 MPa S 6319, Part 2

Flexural strength:

BS 6319, Part 3

Tensile strength:

> 20 MPa

> 9 MPa

0.05 mm

< 20 g/ltr

BS 6319, Part 7

**ASTM D2240** 

Shore D hardness: > 80

Foot traffic: After 24 hr

Vehicular traffic: After 72 hr

Chemical curing: 7 days

Bond strength: 2 MPa (concrete failure)

Maximum wear depth: BS EN 13892-4

Impact resistance: > 10 N.m

ISO 6272-2

#### Method of Use

VOC:

#### **Substrate Preparation**

The substrate must be clean, dry, even, dense and free from oil, grease, dust and other contaminants. A clean surface will ensure maximum adhesion between the substrate and the coating.

Concrete floors must have a minimum compressive strength of 25 N/mm<sup>2</sup> and a maximum concrete relative humidity of 80% (max. moisture content of 4%), relative humidity can be measured by using hygrometers.

Concrete relative humidity should be less than 80% for concrete of 28 days old or more, for low W/C ratio concrete floors, 80% hygrometer reading or less can be achieved before 28 days age.



# Strongcoat Topping Plus

## Surface Preparation

Unsound layers and contaminated concrete surfaces must be prepared using mechanical surface removing equipment. In case of areas deeply contaminated by oil or grease, such areas should be treated with hot compressed air.

#### Priming

Concrete substrates should be primed with Strongcoat Primer. Use lambs wool roller to apply the primer. More than one coat may be required for highly porous or textured surfaces.

Work the primer well into the surface of the concrete and whilst the primer is wet, dress the surface with Antislip Aggregates #3 at the rate of  $0.5 \text{ kg/m}^2$  and allow to touch dry.

Another prime coat shall be applied just before applying the mixed Strongcoat Topping Plus to ensure a strong bond between the primer coat and the top coat.

#### Mixing

Transfer the entire contents of the colour pack into the base container and mix till a uniform colour is achieved. Add the contents of the Strongcoat Topping Plus Hardener into the base container and using a jiffy-type mixer attached to a slow running electric drill, mix for approximately 2 minutes.

Then transfer the entire contents of the base container into a Casco or Creteangle-type mixer, ensuring that the bottom and sides are thoroughly scraped.

Start the mixer and add the entire contents of the Strongcoat Topping Plus Filler container, ensuring that this is completely dry and lump-free. Continue mixing for approximately 2 minutes.

Important: Never mix by hand as this could lead to areas of uncured material.

## Application

Once mixing is complete, transfer the Strongcoat Topping Plus to the uncured primed surface and using a straightedged steel trowel, apply it evenly. The use of Quickmast Solvent when used to clean the trowel will also aid in producing a tight closed surface.

Important: When applying each kit of Strongcoat Topping Plus, leave approximately 200 mm of the closest working edge untrowelled as this will help the blending in of the next kit.

Note: Avoid excessive trowelling as this can lead to marks resembling burns on the surface.

#### Remarks

▲ Strongcoat Topping Plus should not be applied on to surfaces known to suffer from damp rising. Strongcoat Topping Plus should not be applied at temperatures below 10°C or where ambient relative humidity exceeds 80%.

# Sealing

To ensure that the surface is fully sealed against liquid spills, it is recommended that Strongcoat Topping Plus is sealed with two coats of water based Strongcoat WD or solvent based Strongcoat EC10 (see related data sheets for further details).

Note: Please note that the application of a sealer will impair the slip resistance of the floor when subject to wet conditions.

# Cleaning

Strongcoat Topping Plus can be removed by DCP solvent prior setting.

#### **Packaging**

Strongcoat Topping Plus is available in 30 kg packs. Strongcoat Primer is available in 5 kg packs.

## Thickness range

5 - 15 mm and above.

#### Coverage

Strongcoat Topping Plus: Approximately 1.4  $\rm m^2/kit \ @ \ 10 \ mm$  thick.

Strongcoat Primer: 5 m<sup>2</sup>/kg.

#### Storage

Strongcoat Topping Plus and primer have a shelf life of 12 months from date of manufacture if stored at temperatures between 5°C and 30°C.

If these conditions are exceeded, DCP Technical Department should be contacted for advise.

#### **Cautions**

#### Health and Safety

Strongcoat Topping Plus and its primer should not come into contact with skin and eyes.

In case of contact with eyes wash immediately with plenty of water and seek medical advise promptly.

For further information refer to the Material Safety Data Sheet.

## Fire

Strongcoat Topping Plus and its primer are non flammable. DCP solvent is flammable material and should not be used near a naked flame. Do not smoke near DCP solvent.

# Strongcoat Topping Plus

## More from Don Construction Products

A wide range of construction chemical products are manufactured by DCP which include:

- ▲ Concrete admixtures.
- ▲ Surface treatments
- ▲ Grouts and anchors.
- ▲ Concrete repair.
- ▲ Flooring systems.
- ▲ Protective coatings.
- ▲ Sealants.
- ▲ Waterproofing.
- ▲ Adhesives.
- ▲ Tile adhesives and grouts.
- ▲ Building products.
- ▲ Structural strengthening.

# **Strongcoat Topping Plus**



#### Note:

We endeavor to ensure that any advice, recommendation or information we may give in product literature is accurate and correct. However, due to the fact that we have no direct or continuous control over where or how the products are applied, DCP cannot accept any liability either directly or indirectly arising from the use of DCP products, whether or not in accordance with any advice, specification, recommendation or information given by us.